

ecology and environment, inc.

108 SOUTH WASHINGTON, SUITE 302, SEATTLE, WASHINGTON 98104, TEL. 206-624-9537

International Specialists in the Environmental Sciences

PRELIMINARY SITE INSPECTION
REPORT OF OWENS-CORNING
FIBERGLAS CORPORATION
FIBERBOARD PLANT
ST. HELENS, OREGON

TDD R10-8408-31

Report Prepared By: Ecology and Environment, Inc.

Project Leader: Jim Pitts

Date: December 21, 1984

Submitted To: J.E. Osborn, Regional Project Officer
Field Operations and Technical Support Branch
U.S. Environmental Protection Agency
Region X
Seattle, Washington



PRELIMINARY SITE INSPECTION REPORT

Owens-Corning Fiberglas Corporation-Fiberboard Plant TDD R10-8408-31

Site Name/Address

Owens-Corning Fiberglas Corporation (OCFC) Fiberboard Plant Old Portland Road St. Helens, OR 97051

Investigation Participants

James Pitts, Ecology and Environment, Inc. (E&E), Seattle (206) 624-9537 Eileen Black, E&E, Chicago (312) 663-9415

Principal Site Contacts

Marlene Warren, OCFC Facilities Manager (503) 397-0704 Bob Lalande, OCFC Security and Maintenance Supervisor

Date of Inspection

8-30-84, 1400 hours

1.0 Introduction

Owens-Corning Fiberglas has been identified by U.S. Environmental Protection Agency (EPA) Region X and Oregon Department of Environmental Quality (DEQ) from preliminary assessment screening as requiring additional information to accurately profile the nature and extent of past waste disposal activity at the site. Ecology and Environment, Inc. (E&E) has been requested by EPA under Technical Directive Document No. R10-8408-31 to conduct a site inspection and evaluate the facility's status within the agency's Uncontrolled Hazardous Waste Site Program. This report summarizes the results of E&E's preliminary site inspection and is divided into the following sections:

- o Physical Conditions of the Site
- o Climate
- o Geology and Hydrology
- o History of the Site
- o Overview of Facility Process
- o Trip Observations

2.0 Physical Conditions of the Site

Location

The Owens-Corning Fiberglas Corporation's Fiberboard Plant (OCFC) is located at 1645 Railroad Avenue in St. Helens, Oregon. The site is situated in the southeast 1/4 of Section 9, Township 4 N., Range 1 W.; latitude 45°50'50", longitude 122°49'22" (Figure 1) (1).

The plant is located 1 mile south of St. Helens, Oregon, and occupies approximately 175 acres. Scappoose Bay borders the plant on the south and west. Milton Creek is on the eastern border. The area to the north of the plant is undeveloped.

The land use in the vicinity of the plant is considered to be light industry. The plant is served by Burlington Railroad, which has a spur onto the site. It is estimated that the population within a 1 mile radius of the plant is approximately 600.

3.0 Climate

According to the Climatic Atlas of the United States, the St. Helens area receives approximately 48 inches of total precipitation annually with a mean annual lake evaporation rate of 24 inches. About 78 percent of the precipitation falls in the period from October to March. Average maximum 2-year, 24-hour rainfall is 2 inches. The St. Helens area is characterized by a damp, marine-type climate. The warmest months are in July and August with high temperatures averaging 79°F; the coolest months are January and February with low temperatures averaging 34°F.


4.0 Geology and Hydrology

Geology

Two soil types are encountered at the OFCF plant. On the outer fringe of the plant is Sauvie silt loam. The Sauvie series consists of poorly-drained soils formed in recent silty alluvium. Typically, the surface layer is very dark grayish-brown silty clay loam about 15 inches thick. The subsoil is dark grayish-brown mottled silty loam, about 24 inches thick. The substratum is dark grayish-brown mottled very fine sandy loam, about 21 inches thick. Elevations range from 10 to 20 feet (Figure 1). The inner plant area consists of rock outcrop xerumbrepts complex, undulating xerumbrepts parts. Xerumbrepts consist of shallow, well drained, medium-textured soils. Depth to igneous rock is 10 to 19 inches (2).

The soil depth to basalt bedrock in the inner plant area is approximately 19 inches and has a fluctuating water table, which is less than 6 feet below the surface. In the plant outer area the depth to bedrock is less than 60 inches, and the water table is approximately one foot below the surface of the ground (2).

.Arrow points to general vicinity of site



The soil permeability of the inner plant area is 2.5×10^{-2} to 8.4×10^{-2} cm/sec; the outer fringe area ranges from 8.4×10^{-3} to 2.5×10^{-1} cm/sec (2).

Groundwater

There is one registered water well located upgradient in Section 9 near the Owens-Corning plant (Appendix A). The St. Helens Water Department collects water 2.5 miles downstream from the site with two wells located on the bank of the Columbia River. One of the wells is 34 feet deep and the other is 50 feet deep. The wells are 2,000 feet apart (3). The water department serves approximately 5,000 units or a population equivalent to approximately 7,000 people. The analytical results of a groundwater sample from a St. Helens Water Department well, tested for secondary drinking water parameters, are shown in Appendix B. Data on primary drinking water standards for the well are not available.

5.0 History of the Site

OCFC fiberboard plant located in St. Helens, Oregon, was built in 1930. The plant was initially owned and operated by Fir-Tex Insulation Board Company. In November, 1956, Kaiser Gypsum Company purchased the facility and operated it until August, 1978, when OCFC purchased the plant. The plant operation was suspended in December, 1981. The plant has not been in operation since that time, and there are no plans to resume operation (4).

On June 9, 1981, OCFC submitted §103(C) Notification of Hazardous Waste Site Information as required by the Comprehensive Environmental Response, Compensation and Liabilities Act of 1980 (CERCLA) to the Region X EPA (Appendix C). The primary concern of the EPA at the facility is that process chemicals used during the fiberboard production may have entered the groundwater or the Scappoose Bay system. These chemicals may have included: aluminum sulfate, arsenic, asbestos, asphalt, chlorine, clay, gypsum, lime, and soda ash, starch, waste acrylic paint and solvent (4).

6.0 Overview of Facility Process

The process of the production of fiberboard has remained basically the same since 1930. The process of manufacturing fiberboard at Owens-Corning consisted of the following steps (Figures 2,3) (5):

- Wood chips were softened in digesters by steam and chemicals.
- 2. Hot chips were placed in a refiner where they were rolled, rubbed and pulled until the fibers were separated into fiber stock.
- Fiber stock was then sent to the Fourdrinier board-forming machine where the fiber stock was dewatered and formed into board.




FIGURE 2




FIGURE 3
OWENS-CORNING PROCESS FLOW CHART

4. The board was painted, dried and cut into desired lengths.

5. If asphalt board or expansion-joint board were being produced the board would be either sprayed or dipped into an asphaltnaptha solution.

The asphalt board and expansion joint process was discontinued in the early '70's (4).

Waste Generated and Disposal Practices

The different types of waste-generated and disposal practices used by the fiberboard plant are shown in Table 1.

Prior to 1960, the fiberboard plant discharged wastewater to Scappose Bay. A wastewater facility was constructed on-site to handle wastewater produced by the fiberboard manufacturing process. The facility consisted of the following: a primary clarifier constructed of cement, an aeration basin that was rock-lined, and a secondary clarifier constructed of cement. The effluent was then discharged to Scappoose Bay under a NPDES permit (Figure 4).





FIGURE 4 SCHEMATIC OF WASTEWATER FLOW 1960-JUNE 1973

The OCFC fiberboard plant effluent was regulated by NPDES Permit No. OR-200157-1(3479-J) and monitored for flow, pH, biological oxygen demand and chlorine residual. The discharge of the effluent was discontinued when the fiberboard plant operation was suspended in 1981.

TABLE 6.1 TYPES AND DISPOSAL METHODS OF WASTE

Type of Waste	Possible Constituents	Period	Disposal Techniques
Fiberboard process wastewater facility discharge	Fiberboard process wastewater*	1930-1960 1960-1975 1975-1981	Raw wastewater discharged to Scappoose Bay Secondary treated waste water discharged to Scappoose Bay Secondary treated waste water recycled and excess discharged Scappoose Bay
Fiberboard process wastewater with asbestos	Fiberboard process wastewater* with asbestos	1962-1966	Secondary treatment discharge to Scappoose Bay. Asbestos entered sludge (see Table 6.2)
Fiberboard process wastewater with arsenic	Arsenic and fiber- board process waste- water*	1970's period unknown	Secondary treatment discharge to Scappoose Bay. Arsenic information is unavailable.
Wastewater facility sludge	Fiberboard process wastewater* and settleable solids	1930-1960 1960-1973 1973-1975 1975-1980 1980 1983	Raw wastewater with solids discharged to Scappose Bay. Sludge held in aeration lagoon. Sludge held in sludge holding pond and applied to farm land. Sludge recycled back to process. Excess sludge applied to farm land. 400,000 gallons disposed at Santosh Disposal Facility. 7200 cubic yards in on-site holding pond (Figure 7).
Mixed solids	Cardboard, crates, fiberboard scraps, general burnable refuse	1930-1970	Burned on-site

^{*}Fiberboard plant process wastewater and wastewater sludge may include the following chemicals: aluminum sulfate, arsenic, asbestos, asphalt, chlorine, clay, gypsum, lime, soda ash, starch, waste acrylic paint and solvent.



 $1/2 \times 190' \times 205' = 19,475 \text{ sqft}$; 19,475 sqft $\times 10'$ ft* = 194,750 cubic ft. 194,750 cubic ft $\div 27$ cubic ft/yd. = 7,212 cubic yards $\times 10$ foot depth of pond is an estimation

Figure 7
Owen-Corning Fiberglas Fiberboard
Sludge Pond Dimensions

The early design of the wastewater system did not have a provision for disposing of excess solids from the aeration lagoon. This caused an overloaded secondary clarifier and a violation of the discharge permit. This problem was solved in 1973 by removing solids from the aeration lagoon to an unlined, sludge holding pond. These solids were then applied to agricultural land (Figure 5).




FIGURE 5 SCHEMATIC OF SOLIDS REMOVAL JULY 1973

In 1975 the wastewater treatment facility was upgraded. The secondary sludge was returned to the fiberboard forming process, aeration lagoon sludge removed to sludge holding pond, and secondary effluent returned to the fiberboard forming process Figure 6).




FIGURE 6 SCHEMATIC OF UPGRADED PLANT 1975

Characteristics of Waste

In October, 1980, OCFC (formerly Kaiser Gypsum) requested permission to dispose of sludge at the Santosh Disposal Facility located in southwest Columbia County. Permission was granted to dispose of 400,000 gallons of dredge solids from the aeration lagoon. OCFC was requested to test the sludge prior to disposal at the Santosh Disposal Facility.

The amount of sludge remaining in the unlined holding pond is estimated at 7200 cubic yards. There are no plans to dispose of the sludge as of 9/30/84. The sludge from the holding pond and the aeration lagoon were tested in 1980 by Owens-Corning using the EP Toxicity test. The concentrations of metals found in the extract are shown in Table 1.

TABLE 6.2
EP TOXICITY TEST RESULTS

Metals	Sludge Holding Pond	Lagoon Sludge	EP Toxicity Limit (13)
Arsenic	0.01 mg/l	0.003 mg/l	5.0 mg/1*
Antimony	0.002 mg/l	ND	1.0 mg/l
Selenium	0.01 mg/l	<0.001 mg/l	1.0 mg/l

^{*}These values are all below the EP Toxicity limits set for hazardous waste. ND - None Detected

The following concentrations of organics from the EPA priority pollutants were found in the effluent in 1980 by Owens-Corning.

Chemical	Concentration (ug/1)
Methylene Chloride	9.08
Pentachlorophenol	1.126
Di-N-butylphenol	1.52

Owens-Corning believes the pentachlorophenol was applied to some logs as a preservative. By-products from these logs were wood chips and/or sawdust which Owens-Corning used as a raw material in the fiber-board process.

The air emission from the plant operation was regulated by an Oregon DEQ Air Contaminant Discharge permit number 05-2085, which monitored the visible and particulate emissions at the facility. The Oregon DEQ found the facility in compliance and recommended air permits be approved. This permit was initially issued in 1977 and reissued by the Oregon DEQ in 1981 (12).

7.0 Trip Observations

On August 30, 1984, inspectors from E&E met at the OCFC plant in St. Helens, Oregon, with Marlene Warren, facilities manager, and Bob Lalande supervisor of security and maintenance. The following information was provided.

o Plant ceased operation in December 1981. No plans to resume operation.

Wastewater facility is not in operation and there is no dis-

charge.

o Chemicals used at the site were: aluminum sulfate, arsenic, asbestos (1962-1966), asphalt, chlorine, clay, gypsum, lime, soda ash, starch, naptha, waste acrylic paint and solvents, Appendix D.

o Open burning of boxes and scrap occurred until early 1970.

o Treatment plant constructed early 1960's.

Plant on St. Helens city water.

o Lagoon and sludge holding pond are unlined.

o Viewed old photographs.

Plant was on septic system at one time.

o Arsenic use in 1970's.

Some plant machinery is being removed.

Plant had two permits--Air and NPDES.

Plant had a spill prevention plan (SPCC).

After completing the interview, the inspectors toured the plant and wastewater facility.

The wastewater facility was not in operation, and there was no discharge. The sludge holding pond was observed to be nearly full. The sludge was dry and very fiberous. There has not been any additional sludge added to the pond since 1981. There are no current plans to dispose of the remaining sludge stored at the facility.

After completing the tour of the facility, the inspectors returned to the plant office. The inspectors left the site at 1700 hours.

SITE EVALUATION AND RECOMMENDATIONS OWENS-CORNING FIBERGLASS CORPORATION

Site Evaluation

There are approximately 7200 cubic yards of sludge in the plant holding pond (Figure 7). There are no plans by Owens-Corning to remove the sludge from the site.

EP toxicity test results from 1981 indicate that the sludge does not exhibit hazardous waste characteristics.

The leaching tendency of selected metals from the sludge has been demonstrated by the EP toxicity test. It is possible that these chemicals have migrated into the groundwater below the site and into the shallow aquifer. No sampling has been conducted since 1981. All discharges of wastewater effluent have ceased since 1982.

Recommendations

The available inorganic or organic analytical data does not appear to indicate a hazard from the leaching or discharge of contaminants from the sludge holding pond. However, current sampling data from the sludge pond should be considered to confirm earlier sampling along with sampling nearby drinking water wells and Scappoose Bay on a low priority basis.

Site Evaluation and Recommendations

Owens-Corning Fiberglas Corporation

Site Evaluation

There are approximately 7200 cubic yards of sludge in the plant holding pond (Figure 7).

There are no plans by Owens-Corning to remove the sludge from the site.

EP Toxicity test results indicate that the sludge does not exhibit hazardous waste characteristics.

The leaching tendency of selected metals from the sludge has been demonstrated by the EP Toxicity test. It is possible that these chemicals have migrated into the groundwater below the site and into the shallow aquifer. No sampling has been conducted since 1981. All discharges of wastewater effluent have ceased since 1982.

Recommendations

The available inorganic or organic analytical data does not appear to indicate a hazard from the leaching or discharge of contaminants from the sludge holding pond. (Additional sample collection from the sludge pond may be considered on a low priority basis if confirmation of the earlier results provided by OCFC is desired.) The results of available analytical data indicates that the sludge currently stored at the facility is considered to be non-hazardous under RCRA and as such no further actions should be taken at the site.

Rich martixions

REFERENCES

- 1. USGS St. Helens Quadrangle, Photo Revised 1970.
- 2. Soil interpretation record, Columbia County USDA-SCS,06-81, E&E file.
- 3. Phone conversation with Mr. Nate Waldron, St. Helens Water Department, 8/22/84.
- 4. Ecology and Environment, Inc., Site Inspection 8/30/84.
- 5. Kaiser Gypsum Company, tour pamphlet.
- 6. Memo. DEQ to Kaiser Gypsum, July 23, 1973. Summary of Status of the Wastewater Treatment System.
- 7. Rolf Larson Excavating, Letter, April 29, 1974. Acceptance of sludge for disposal on his property (E&E file).
- 8. Letter from Kaiser Gypsum to Oregon DEQ, June 7, 1974. Sludge disposal on Miller's property.
- Letter from Kaiser Gypsum to Oregon DEQ, March 14, 1975. Treatment plant upgrade.
- 10. Letter from Oregon DEQ to Santosh Disposal Corporation, November 10, 1980. Authorization to dispose of dredge solids from Owens-Corning Fiberglas Corporation.
- 11. Owens-Corning Fiberglas Discharge Monitoring Report, EPA Form 3320-1.
- 12. Air Contaminant Discharge Permit Application Review Report, 8/25/81.
- 13. Federal Register, May 19, 1980, EP Toxicity Standards.

LIST OF APPENDICES

- APPENDIX A WELL WATER REPORT STATE OF OREGON TOWNSHIP 4W, RANGE 1W, SECTION 9
- APPENDIX B REPORT OF ANALYSIS OF DRINKING WATER FOR SECONDARY CHEMICAL CONTAMINANTS
- APPENDIX C 103(C) NOTIFICATION OF HAZARDOUS WASTE SITE
- APPENDIX D PLANT SURVEY AT KAISER GYPSUM SEPTEMBER 16, 1969
- APPENDIX E SLUDGE CHEMICAL ANALYSIS SUBMITTED FOR DEQ APPROVAL OCTOBER 31, 1980
- APPENDIX F SITE INSPECTION FORM

APPENDIX A

NOTICE TO WATER WELL CONTRACTOR The original and first copy of this report are to be filed with the

STATE ENGINEER, SALEM. OREGON 97310 within 30 days from the date of well completion.

WATER WELL RIPORT CENTRE Well No. 1010 (Please type or pust ATE ENGINEER ermit No. (Do not write above this SALEM CREGON

(1) OWNER:	(10) LOCATION OF WELL:
Name Brian L. Miller	_
Address 2185 Gable Road St. Helens, Orc.	County Columbia Driller's well number
	"4 14 Section Q T: 4-19 R. 1-19 W.1
(2) TYPE OF WORK (check):	Bearing and distance from section or subdivision corner
New Well Deepening Reconditioning Abandon	
If abandonment, describe material and procedure in Item 12.	
	(11) WATER LEVEL: Completed well.
Potent El Potent	Depth at which water was first found 20
Cable	Static level 18 ft. below land surface. Date 2-7-73
Bored I Irrigation Test Well Other	7
(>) CASING INSTALLED: Threaded [] Welded 2]	Artestan pressure lbs. per square inch. Date
(5) CASING INSTALLED: Threaded Welded 2	(12) WELL LOG: Diameter of well below casing _6
	Depth drilled 140 ft. Depth of completed well 140 ft
Diam. from	Formation: Describe color, texture, grain size and structure of materials
Diam. fromft. toft. Gage	
(v) PERFORATIONS: Perforated? Tyes 42 No.	with at least one entry for each change of formation. Report each change in position of Static Water Level and indicate principal water-bearing strate
Type of perforator used	
	MATERIAL From To SWL
	Top soil 0 3
perforations from ft. to ft.	
perforations from ft. to ft.	Brown Lava rock 28 35
perforations from ft. to ft.	Blue hard rock 35 125
(7) SCREENS: Well screen installed? Yes W No	Blue broken rock 125 140
Manufacturer's Name	
Type Model No	
Diam. Slot size Set from ft. to ft.	
Diam. Slot size Set from ft. to ft.	
(8) WELL TESTS: Drawdown is amount water level is lowered below static level	
Was a pump test made? [] Yes ② No If yes, by whom?	
	[
air .	
XXXXX test 8 gal./min. with /02 ft. drawdown after / hrs.	
sian flow g.p.m.	
perature of water Depth artesian flow encountered ft.	Work started 2-7-73 to Completed 2-7-73
	Completed 2 / / / 19
(9) CONSTRUCTION:	Date well drilling machine moved off of well 2-/-/3
Well seal-Material used Cenent	Drilling Machine Operator's Certification:
Well sealed from land surface to 18'-6"	This well was constructed under my direct conservation
Diameter of well bore to bottom of seal	
Diameter of well bore below seal	best knowledge, and belief [Signed] Signed Date 2-10-73 19 [Drughig Machide Operator)
Number of sacks of cement used in well seal 2 sacks	(Drilling Machine Operator)
Number of sacks of bentonite used in well seal sacks	Drilling Machine Operator's License No. 254
Brand name of bentonite	W. A III 11 G
Number of pounds of bentonite per 100 gallons	Water Well Contractor's Certification:
of water lbs./130 gals.	This well was drilled under my jurisdiction and this report is
Was a drive shoe used? ☐ Yes ♣ No Plugs Size: location ft.	true to the best of my knowledge and belief.
Did any strata contain unusable water? Tyes & No	Name Kalph Junior Dailing 0. (Person, firm or corporation) (Type or print)
Type of water? depth of strata	Address Rtc 1 Box 141 Hillsbaro, Gregon
Method of sealing strate off	000
Was well gravel packed? ☐ Yes ₹ No Size of gravel:	[Signed] Stalfel Junion
Gravel placed from	(Contractor)
11. 10	Contractor's License No247 Date2-10-73

APPENDIX B

Yeater Chemistry	4
Bacteriology	
EPA Certified	W.
State Certified	7



Water A≥glysis & Consulting, Inc. 304 BLAIR BEVD. • EUGENE, OREGON 97402 503-485-8404 SECRESTY SEN

Lab Report No	045249		
Inv. No.:	2210		
	744		
Cust. PO No.:			

REPORT OF ANALYSIS OF DRINKING WATER FOR SECONDARY CHEMICAL CONTAMINANTS*

NAME City of St. Helens,	COLLECTED 3/2/84	BY_Cu	stomer
ADDRESS P.O. Box 278	RECEIVED 3/5/84	TIME	
St. Helens, OR 97051	ANALYZED "	TIME	
WATER SYSTEM Same		SOURCE	Well

CRITERIA

Physical & Chemical	Max All Concent		Desirable	Test Results
Chlorides	250	mg/l	< 25 mg/l	10 mg/l
Copper	5.0	mg/l	NONE	0.23 mg/l
Hardness (as CaCO ₃)	250	mg/l	< 60 mg/l	88 mg/l
Iron	0.3	mg/l	NONE	0.03 mg/1
Manganese	0.05	mg/l	NONE	0.02 mg/1
рH	6.5	<	7.0-8.0	6.7
Solids: (Residue) Filterable ("Total Solids") Nonfilterable ("Sand")	500 2.0	mg/l mg/l	<100 mg/1 NONE	170 mg/1 2 mg/1
Specific Conductance				170 µmho/cm
Sulfates	250	mg/l	25 mg/l	1 mg/1
Total Dissolved Solids (Est)	500	mg/l	<100 mg/1	110 mg/1
Zinc	5.0	mg/l	<0.5 mg/l	<u><0.01</u> mg/1

*(OAR Chapter 333/Section 42-210 revised 2/82)

3/15/84 Date ____

APPENDIX B

nalysis of: Unter Seguri	- 17 5	Vater Analysis & Consulting, I		b Report No:	
Anna Waste		304 BLAIR BLVD.			2210
ميروسي. الينامك		EUGENE, OREGON 97402 503 485-8404	CL	istomer PO No:	
			OSIVITY		
AME	City of St		SOURCE Columb	oia River/Ram	ney Collect
_	S P.O. Bo		LOCATION City		
•	St. Hel	ens, OR 97051	DATE COLLECTED		Y Custome
AMPLI	ERS: CUSTOM	ER	DATE ANALYZED		
				Tes	t Results
)	CORROSIVIT	Y: LANGLIER SATURAT	TION INDEX		L_6*
)				_	
)	Filterab	le Solids		170	mg/1
)					
)	pН				5.7
)	•				
)	Temperat	ure		_1;	2°c
)				<u> </u>	
)	Alkalini	ty	•	78	mg/1-
)			•		
)	Calcium	Hardness	,	_ 88_	mg/l
)					
)	*Modera	tely aggressive wate	r		
)	•	·			
) . \					
<i>)</i>					
, \		•			
,					
, ,			•		
, \					
, 1					
, \	•			-	· ·
, γ.			·	-	
, ,		•	•		
,)			•		
Ś		•			
΄.				·	
					

APPENDIX C

`	Notificati	or of	Hazardous	s Waste Site			Agency	mental Protectio
	The same manifestion of condi- tation to the condition of the condi- tation to the condition of the con- traction and county Act of 1900 to man and by sum of 1900.	pen-	willer applies.	e separate sheets of etter of the item			Aff.	
			<u></u>	nigh HAZARd= 95	<u>9</u> 4025	000	001	032)
Ā	Person Required to Notify:		Name Owens-Cor	ning Fiberglas Co	rnorat	ion		
•	Enter the numer and address of the organization required to notity.	ne person		Tower				
			Civ Toledo		State	Ohio	Zip Code	43659
В	Site Location:							
	dinter the common name (if know actual location of the site	n) and		-Corning Fibergla Portland Road				
			Cw St. Helens					97051
\overline{c}	Person to Contact:	···						
	Enter the name, title (if applicable business telephone number of the to contact regarding information submitted on this form.		Name (Last, First and Title Phone	(419) 248-8220		squire		
D	Dates of Waste Handling: Enter the years that you estimate treatment, storage, or disposal be- ended at the site.	waste gan and	From(Year) 1930	To (Year) Prese	nt		<u> </u>	
Ε.	Waste Type: Choose the optio Option I: Select general waste typy you do not know the general wast encouraged to describe the site in	es and so e types or	urce categories. If sources, you are	Option 2: This option Resource Conservation regulations (40 CFR I	on and Re	covery Ac	sons farr t (RCRA)	niliar with the Section 3001
	General Type of Waste: Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.	Source of Place and boxes.	f Waste: K in the appropriate	Specific Type of Wa EPA has assigned at listed in the regulation appropriate four-digit the list of hazardous contacting the EPA R	our-digit ns under number wastes ar	Section 3 in the box nd codes o	001 of R es provid an be of	ICRA. Enter the led. A copy of plained by
	1. Organics	1. D Mir	•	located.			•	
	2. ☐ Inorganics 3. ☐ Solvents	2. ☐ Cor	struction					
	4. 🗆 Pesticides	4 G Fer	1				<u> </u>	
	5. ☐ Heavy metals	5. 🗆 Pap	er/Printing					
	6. ☐ Acids 7. ☐ Bases		ther Tanning					
	8. C PCBs		/Steel Foundry		<u></u>			
	9 C Mixed Municipal Waste		ing/Polishing		<u> </u>		<u> </u>	
	10. XXUnknown		tary/Ammunition	 			 -	
			trical Conductors	<u> </u>	 -		<u> </u>	
		12. 🖾 Trad						
			ity Companies iitary/Refuse	. •				
		15. 🗆 Pho		14. Eth #14	" ()			*9
		16. 🗆 Lab		K 14.				
			er (Specify)	## £5°	31			
		Product	od Fiber	G - Project	:t. ≥ X			
	Form Approved OMB No. 2000-0138				••			

APPENDIX C

	Notification of Hazardous Was* Site	Side Two	
	Waste Quantity:	Facility Type	Total Facility Waste Amount
	Place an X in the appropriate boxes to indicate the facility types found at the site.	1. Piles	See site description (Section 1)
	In the "total facility waste amount" space	2. Land Treatment 3. Landfill	gallons (SECTION 1)
	give the estimated combined quantity (volume) of hazardous wastes at the site	4. 🗆 Tanks	Total Facility Area
	using cubic feet or gallons.	5. 🗆 Impoundment	• •
	In the "total facility area" space, give the	6. Underground Injection	See site description be
	estimated area size which the facilities occupy using square feet or acres.	7. Drums, Above Ground 8. Drums, Below Ground	(Section I)
		9. XX Other (Specify) Wastewa	ter Treatment
-	Known, Suspected or Likely Releases to	the Environment:	
	Place an X in the appropriate boxes to indicate or likely releases of wastes to the environmen	any known, suspected,	☐ Known ☐ Suspected XXII Likely ☐ Non
	Note, items Hand I are optional. Completing hazardous waste sites. Although completing	these items will assist EPA and State the items is not required, you are end	and local governments in locating and assessing
ī			
	Sketch a map showing streets, highways,	•	
	routes or other prominent landmarks near the site. Place an X on the map to indicate		
	the site location. Oraw an arrow showing the direction north. You may substitute a		
	publishing map showing the site location.		
			•
			•
		•	•
		•	•
		• *	
	•		
_			<u> </u>
	Description of Site: (Optional)		
	Describe the history and present conditions of the site Give directions to the site and describe any nearby wells. springs lakes, or housing include such information as now waste was disposed and where the waste came from Provide any other information or comments which may help describe the site conditions. for eventual reuse as process may where it is regulated by an disposed of within the approval	St. Helens Plant is qui small amounts of variou been used at the Plant entered the water syste process or intentional treatment operation wou ke-up water or it would be N.P.D.E.S. permit. Sludge	from the lagoon has been
	rsuch as plant managers; superintendents, trustees or attorneys) of persons required	Owens-Corning Fibergla Signary Toledo Signary	S Corporation
	Check the boxes which best describe the relationship to the site of the person	grature next Kruty	Operator, Past D Other

APPENDIX D

101 Mas. Couch Street, Portima, Greek 1 97232

MEMORANDUM

TO:

Wayne Hanson Lo

rs. Do All

FROM:

Tom Bispham 73

SUBJECT: Plant Survey at Kaiser Gypsum, St. Helans, Oregon

On 16 September 1969, Bob Harris and myself met with Mr. Jack Cassidy, Plant Manager of Kaiser Gypsum. Our purpose was to inform Mr. Cassidy of the recent odor complaints and conduct a plant survey for the identification of other possible sources of air pollution. This plant produces a variety of items ranging from basic wood fiber board to mineral wool board. The products are used for acoustical and insulating properties.

Plant Survey

This plant employes 250 people and some phase of operation, if not the entire plant, is in production 365 days per year.

Eoilers

Three automatic Erie boilers are operated in series, each producing 20,000 lbs/of steam.

Coen burners.

Operators do not have a view of the stack nor a means of emission detection.

• Fuel used is natural gas with bunke. C oil for standby. In August 1969, 712,000 therms were burned which is probably close to an average monthly consumption. Fuel costs average close to \$1000/day. During a normal year the plant may be on oil for approximately 25-30 days.

Basic Board Production

Basic board is the main production item of this plant. With an exception of four days per month when the plant is producing mineral wool board, basic board production will be conducted 24 hrs/day, 7 days/week. Capacity is 150 tons/day (050,000 sq. ft.) or 10 million sq.15/ms. of 3/6" to 1" thickness.

Raw materials are simply sawdust and wood chips (Douglas fir, spruce, hemlock, and white fir). Process flows is described on the attached sheet.

Remanufacturing

Of the 150 tons of basic board produced daily, 75 tons is shipped and the remaining 75 tons will undergo some form of remanufacturing. The various remanufacturing process is described below.

Tile Lines

Prior to entering the tile line, basic board is passed through a planer, V-jointer, and a calender machine (coating applicator, water soluble). The fibers

APPENDIX D

Memorandum - Kaiser ,psum Page 2 26 September 1969

. >

from the planer and jointer are vented through the heading cyclone. The calender machine present no problem.

These tele lines are utilized for the manufacturing of lay-in board for acoustical ceilings, planks, and mobile home ceilings. This operation is conducted 5 days/week, 2h hours/day. Lines #1 and #2 are identical; the basic board undergoing cutting, painting, drying, recutting, and wrapping. Emission from cutting are vented to a 12' diameter cyclone. As water base paint is used, no problem is created. Fifteen tons/day is processed in these lines, namely items such as lay-in ceiling tile.

Tile line #3 is basically the same as #1 and #2 except the only product is 4' ceiling board which is used in mobile homes. The resaw on this line is vented to a 10' diameter cyclone. 45 tons/day is processed thru this line.

It is unknown at this date whether these cyclones are in compliance.

Asphalt Coating

Basic board from the headrig is removed to a building used expressly for asphalt coating. The board is passed through an uncontrolled asphalt saturator (both sides saturated), cooled by water and conveyed to the wrapping area. (Some resawing occurs here, the dust being vented to a small cyclone and then to the headrip cyclone. This operation takes place 1-2 dys/wk for 8 hour periods. Fifteen tons/day is processed.

Expansion Jointing

Pasic board is again removed to a separate building for this operation. The board is immersed in a tank containing asphalt and a naptha solvent. It is then dried on a steam heated kiln. The oders from the coating and drying operation emit extremely strong odors. This 8 hr. operation occurs 2-3 days per month. This gaint is used on sidewalks, etc.

Mineral Wood Board

Mineral wool board is one item produced which is also used for ceilings and insulation. Its desireable qualities are that it is non-combustible and stronger than baser board. Production occurs approximately h days per month. Capacity is 150 tons/day. As mentioned before, when this item is in production, basic board production is down, as the same manufacturing and control equipment is used.

The raw materials used are, mineral wool, clay and starch. They are introduced into the Fourdinier board forming machine Kassacked on the flow char)

Memorandum - Kaiser ,psum Page 3 26 September 1969

Paint

Kaiser Gypsum mixes its own paints. This is a water base paint and presents no air pollution problem. 60,000 gallons are produced each month.

Waste disposal

Currently approximately 2 cubic yards of paper sacks and crates are generated daily. Kaiser Gypsum is disposing of this waste by open burning.

Air Pollution Problems

Open burning - Mr. Cassidy was informed that this is a problem which we expected him to clear up as soon as possible. Although the area is out of the public's sight, Kaiser Typsum does employ a large number of people who are aware of this practice. He informed us that his desire is to utilize his waste by installing a hydropulper and putting the residue back into the process. We informed him that the time required for approval, 3 months, was too long and that we expected him to use total haulaway and would be applying the appropriate pressure to do so.

Odor - Extremely strong odors are emitted from both the asphalt saturator and expansion joint operation. This problem is one which the Columbia County Health Department is retieving complaints. Kaiser Gypsum is in hopes of discontinuing this line. However, no date is foreseeable. Mr. Cassidy was told that odor surveys would be conducted.

Opacity

Mr. Cassidy was told that in all probability that the asphalt saturator was in violation. However, reading have never been taken. This will be done in the near future.

Also the cyclone emissions have never been documented. This is also scheduled in the near future.

The following control program was outlines to Mr. Cassidy:

Field personnel would conductedor surveys and opacity readings on the sources which appeared to be a problem. When the problem areas have been clearly defined to our satisfaction, CWAPA representatives would meet with Kaiser Gypsum and outline these areas and what we expected from Kaiser Gypsum.

This program was acceptable to Mr. Cassidy. As several of these sources are within the plant, he requested we check in with the office when travelling through the plant.

In his absence, contact Assistant Manager Murel Kontny.

ATTACHMENT ATTACHMENT

EXPRESS MAIL

Cctober 31, 1980

%r. Charles Gray
%regon Dept. of Environmental Quality
2.0. 8ox 1760 Portland, Oregon 97207

Re: St. Helens - Solid Waste

Dear Mr. Gray:

Following up on our conversation October 30, 1980, we have provided below the additional information you requested to enable you to approve disposal of our pond dredgings at Scapoose.

1. Quantity

We have an immediate requirement to dispose of about 400,000 gallons of dredgings. This will be a recurring need but it is difficult at this time to project quantities and timing.

2. General Description

Attached lab results show % solids and % volatile solids in the dredgings. The % volatile solids represents the presence of organics from the wood pulp in the pond bottoms.

3. Metals

Samples of sludge and accration pond dredging were subjected to USEPA EP extraction and the extract analyzed for metals as follows (ND is none detected - limit 1 µg/l)

Metal (mg/l)	Sludge Pond	<u> Aeration Pond</u>
Barium	ND	ND
Cadmium	ND	ИD
Chromium	ND	ND
Lead	ND	ND
Silver	· ND	ND
Arsenic	0.01	0.003
Selenium	0.01	<0.001
Mercury	ND	ND
Antimony	0.002	ND

APPENDIX E

October 31, 1980 Page 2

Charles Gray - Portland, Oregon

4. <u>Toxic Materials</u>

Effluent sample was checked for all organics on the 129 priority pollutant list. Only the following were detected.

Number		Chemical	(parts	ug/l per billion)
44. 64. 68.	•	Methylene Chloride Pentochlorophenol Di-N-Butylphthalate		9.08 1.126 × 1.52

We consider these results to be a credit to the power of modern analytical techniques and essentially a clean-bill of health for our waste.

From our sampling of other water, we would classify the methylene chloride and phthalate ester as low background. Pentochlorophenol is a wood preservative and could be tramp in the sawdust or wood chips we use.

Sincerely,

GHENS-CORNING FIBERGLAS CORP.

C. A. Harrison CAH:dg

bcc: Dennis Barcheski - St. Helens Bruce Paskett - St. Helens S. H. Thomas - BT/552

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 1 - SITE LOCATION AND INSPECTION INFORMATION

I. IDENTIFICATION
OI STATE 02 SITE NUMBER
OR D0903476109

37	PART 1 - SIT	E LOCATION AND	INSPE	CTION INFORM	ATION LOIL	100303470103	
I. SITE NAME AND LOC	ATION		· · · · · ·			·	
11 SITE NAME (Legal, common, o	·		02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER				
I .	ng Fiberglas Corp	•	Old Portland Road				
D3 CITY		-	1	05 ZIP CODE	08 COUNTY	07COUNTY 08 CONG CODE DIST	
St. Helens			OR	97051	Columbia	07COUNTY 08 CONG CODE DIST 009 03	
09 COORDINATES 4 5 5 0 5 0 0	10 TYPE OF OWNERSH XA. PRIVATE F. OTHER			C. STATE D. COUNT	TY E. MUNICIPAL		
II. INSPECTION INFORM							
O I DATE OF INSPECTION	02 SITE STATUS	03 YEARS OF OPERA		5 01			
8 ,30 , 84 MONTH DAY YEAR	☐ ACTIVE EXNACTIVE	19	30 Inning yea	1 Dec 81	UNKNOW!	N	
4 AGENCY PERFORMING INS	PECTION (Check as that appry)] BEG	NNING YEA	R ENDING YEAR		·	
□ A.EPA 2018.EPAC	ONTRACTOR ECOLOGY	& Environmen		ÌNICIPAL □ D. M HER	UNICIPAL CONTRACTOR _	(Name of Sum)	
	· · · · · · · · · · · · · · · · · · ·	lame or firms	<u> </u>	rich	(Specity)		
5 CHEF INSPECTOR	•	OB TITLE	T	1 1	07 ORGANIZATION	08 TELEPHONE NO.	
James Pitts		Inspection	ıeam	Leader	E&E	(206) 624-9537	
8 OTHER INSPECTORS		10 TITLE			11 ORGANIZATION	12 TELEPHONE NO.	
Eileen Black		Inspection	Team	Member	E&E	(206) 624-9537	
						()	
						()	
				· · · · · · · ·		()	
				· · · · · · · · · · · · · · · · · · ·			
	•					()	
3 SITE REPRESENTATIVES IN	TERVEWED	14 TITLE Facil	ity	SADDRESS		16 TELEPHONE NO	
Marlene Warren	···	Manager		1645 RR Ave	e St. Helens	(503) 397-0704	
Bob Lalande		Security & Maintenance	e .	1645 RR Ave	e St. Helens	(503) 397-0704	
						()	
						()	
						()	
						()	
FACCEES GAINED BY	18 TIME OF INSPECTION	19 WEATHER COND	TIONS				
XXPERMISSION I WARRANT	1400 hrs.	Clear 6	0°				
. INFORMATION AVAIL	ABLEFROM					1	
CONFACT		02 OF (Agency-Organiz	alion)			03 TELEPHONE NO.	
Debbie Flood				otection A		(206) 442-2722	
James Pitts	N SILE MISHECTION FORM	FIT/EPA	E&E	ANIZATION - -	624-9537	11 , 20 84	
EPA FORM 2070-13 (7-81)		1			<u>'</u>		

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 2 - WASTE INFORMATION

I. IDENTIFICATION
O1 STATE O2 SITE NUMBER
OR D093446109

	TATES, QUANTITIES, AN			1	0.07.05		
O1 PHYSICAL S XM A. SOLID M B. POWDE XM C. SLUDGI		TONS .	TY AT SITE If waste quantities If waste quanti	O3 WASTE CHARACTE A. TOXIC B. CORROL C. RADIOA D. PERSIST	E. SOLU SIVE D F. INFEC CTIVE D G. FLAM	BLE I I HIGHI TIOUS II J. EXPL MABLE II K. REA ABLE II L INCO	
C D. OTHER	· Saeciivi	NO. OF DRUMS	≅ 30 	ignitable	if dry	U M. 1401	AFFORABLE
II. WASTE T	YPE						
CATEGORY	SUBSTANCE N	AME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS		
SLU	SLUDGE	_	7212 (est)	Cubic yard		Solids (Dry	Solids)
OLW	OILY WASTE						
SOL	SOLVENTS						
PSD	PESTICIDES						
000	OTHER ORGANIC CH	EMICALS				, 	
100	INORGANIC CHEMIC			-		-	
	ACIDS						
ACD	BASES						
BAS MES	HEAVY METALS		· · · · · · · · · · · · · · · · · · ·				
	OUS SUBSTANCES (See A)			<u>. </u>			
	02 SUBSTANCE N		03 CAS NUMBER	04 STORAGE/DISF	OSAL METHOD	05 CONCENTRATIO	06 MEASURE OF CONCENTRATION
1 CATEGORY			7440-38-2				
SLU	Arsenic		7782-49-2	sludge pon		10.	ug/1 ug/1
SLU	Selenium		7440-36-0	sludge pon sludge pon		2.	ug/1
SLU	Antimony						
SLU	Methylene chlor	ride	75-09-2	discharged		e 9.08	ug/1
			07.06.5		Bay		
SLU	<u>Pentachloropher</u>		87-86-5	H 1		1.126	ug/]
SLU	Di-N-Butylphtha	late	84-74-2	11 1		1.52	ua/1
<u> </u>			1332-21-4				
Unk	Asbestos used	(62-66)	ļ	Unknown		Unknown	<u> Unknown</u>
<u></u>			<u> </u>				
	Analysis provid			iberglas to	uregon Depa	rtment of	
	Environmental (Quality -	Oct 1980				_
/ FEEDSTO	CKS (See Appendix for CAS Number			I		L	
			02 CAS NUMBER	CATEGORY	01 FEEDSTO	OCK NAME	02 CAS NUMBER
CATEGURY	01 FEEDSTOCI	NAME	UZ CAS NOMBEN	FDS			
FDS			 		N/A		
FDS	N/A			FDS	N/A		+
FCS		 	ļ	FDS			
FDS			<u> </u>	FDS			1
/I. SOURCE	S OF INFORMATION (Ca)	specific references. e.g.	, state fires, \$ambie analysis.	eportsi			
Amount estimat	hemical analysis of sludge prese ed 10ft. depth and Environmen	nt is an e (See Fig.	estimation ta	iken trom aei	rial photogi	raphs with a	

POTENTIAL HAZARDOUS WASTE SITE: SITE INSPECTION REPORT PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER

OR D093476109

. HAZARDOUS CONDITIONS AND INCIDENTS 01XZ A. GROUNDWATER CONTAMINATION	02 OBSERVED (DATE:		A POTENTIAL	O ALLEGED
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION)	'LI' POTENTIAL	□ ALLEGED
agoon is unlined.				
01 🖔 B. SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED:	02 G OBSERVED ICATE04 NARRATIVE DESCRIPTION		XXPOTENTIAL	☐ ALLEGED
reek west and north of site, run	off from site could enter	Scappo	ose Bay	
01 ☑ ℃. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED:	02 G OBSERVED (DATE:)	☐ POTENTIAL	C ALLEGED
sphalt process used Naptha which rocess discontinued.	n caused complaints from resi	dents	in early	1970.
D1 ☐ D. FIRE:EXPLOSIVE CONDITIONS D3 POPULATION POTENTIALLY AFFECTED:	02 OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED
	•		:	
•	· .			
01 □ E. DIRECT CONTACT 03 POPULATION POTENTIALLY AFFECTED:	02 OBSERVED (DATE: 04 NARRATIVE DESCRIPTION		☐ POTENTIAL	☐ ALLEGED
3 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION	ence.	☐ POTENTIAL	C ALLEGED
rea is not fenced on water bound The state of the state	04 NARRATIVE DESCRIPTION	ence.	☐ POTENTIAL	
DIS POPULATION POTENTIALLY AFFECTED: The anis not fenced on water bound The anis not fenced on water	04 NARRATIVE DESCRIPTION Iries. Thick brush acts as f	ence.		
DI G. DRINNING WATER CONTAMINATION	04 NARRATIVE DESCRIPTION Iries. Thick brush acts as f) ence)		
POPULATION POTENTIALLY AFFECTED: rea is not fenced on water bound of G. Contamination of Soil of AREA POTENTIALLY AFFECTED: (Acres) Of G. DRINNING WATER CONTAMINATION OF POPULATION POTENTIALLY AFFECTED: ne known well in Section 9. (See	04 NARRATIVE DESCRIPTION dries. Thick brush acts as for the second seco)) wens -(O POTENTIAL Orning File	C ALLEGED Derglas
POPULATION POTENTIALLY AFFECTED: rea is not fenced on water bound of G. F. CONTAMINATION OF SOIL OF AREA POTENTIALLY AFFECTED: (Acres) OF CONTAMINATION OF SOIL (Acres)	04 NARRATIVE DESCRIPTION dries. Thick brush acts as for the second seco)) wens -(O POTENTIAL Orning File	C ALLEGED Derglas
The worker exposure injury affected: Contamination of Soil	O2 COBSERVED (DATE: O4 NARRATIVE DESCRIPTION O2 COBSERVED (DATE: O4 NARRATIVE DESCRIPTION Site Inspection Report on Opendix A). No wells downgra)) wens -(OPOTENTIAL Corning Fill of the si	C ALLEGED berglas te.
or population potentially affected: irea is not fenced on water bound or solution of solution affected:	O2 COBSERVED (DATE: O4 NARRATIVE DESCRIPTION O2 COBSERVED (DATE: O4 NARRATIVE DESCRIPTION Site Inspection Report on Opendix A). No wells downgra)) wens -(OPOTENTIAL Corning Fill of the si	C ALLEGED berglas te.

SEFA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

ļ	÷	IDE	וא	(F1	CA	110	N		
ı	01	STA	TΕ	02	SIT	E NL	JM8	EΑ	
ł	10	STA R	- 1	DO	ງ9	34	76	10	C

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS II. HAZARDOUS CONDITIONS AND INCIDENTS (Community ☐ ALLEGED ☐ POTENTIAL 02 COSSERVED (DATE: _ 01 J. DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION None 02 GOBSERVED (DATE. __ ☐ POTENTIAL ☐ ALLEGED 01 E K. DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION (Include name) of species) None DE COBSERVED (DATE. 4/29/74) 01 XXL. CONTAMINATION OF FOOD CHAIN XX POTENTIAL ALLEGED 04 NARRATIVE DESCRIPTION Sludge was applied to farmland. 1 OBSERVED (DATE: _ ☐ POTENTIAL 01 DM. UNSTABLE CONTAINMENT OF WASTES **DA MARRATIVE DESCRIPTION** 03 POPULATION POTENTIALLY AFFECTED: ☐ ALLEGED 01 II N. DAMAGE TO OFFSITE PROPERTY 102 1 OBSERVED (DATE: __ □ POTENTIAL **04 NARRATIVE DESCRIPTION** None 01 - 0 CONTAMINATION OF SEWERS, STORM DRAINS, WWITH 02 - OBSERVED (DATE: ☐ ALLEGED ☐ POTENTIAL 04 NARRATIVE DESCRIPTION None 2 COBSERVED (DATE. _ □ POTENTIAL □ ALLEGED 01 C P. ILLEGAL UNAUTHORIZED DUMPING **04 NARRATIVE DESCRIPTION** Unknown 05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS None III. TOTAL POPULATION POTENTIALLY AFFECTED: 9.000-10.000 IV. COMMENTS Lagoon is unlined, leachate from lagoon would enter Scappoose Bay. Sludge was applied to farmland. Runoff from site could enter Scappoose Bay. V. SOURCES OF INFORMATION (Cité specific references, e.g., 21300 (1905) analysis, reports: Interview with facilities manager; well logs from State of Oregon; Owens-Corning Fiberglas Report on Sludge Analysis.

8 m	
- ABS	Communication of The Communica
Ø. 3	17 6

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

	IFICATION
OR STATE	0093476109

PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA IL DRINKING WATER SUPPLY 02 STATUS 03 DISTANCE TO SITE 01 TYPE OF DRINKING SUPPLY ENDANGERED AFFECTED MONITORED SURFACE WELL 2.5 8. 🗆 C.XX B.XX A. 🗆 (mi) COMMUNITY A. 🗆 D. 🗆 E. 🗆 F. 🗆 (m) NON-COMMUNITY C. 🗆 D.XX III. GROUNDWATER 01 GROUNDWATER USE IN VICINITY (Check one C. COMMERCIAL, INDUSTRIAL IRRIGATION [] D. NOT USED, UNUSEABLE A. CNLY SOURCE FOR DRINKING XX8. DRINKING COMMERCIAL, INDUSTRIAL, IRRIGATION unknown 03 DISTANCE TO NEAREST DRINKING WATER WELL 02 POPULATION SERVED BY GROUND WATER _ 06 DEPTH TO AQUIFER OF CONCERN 08 SOLE SOURCE AQUIFER 05 DIFFECTION OF GROUNDWATER FLOW 07 POTENTIAL YIELD 04 DEPTH TO GROUNDWATER ☐ YES ☐ NO unknown (apdi <u>east/southeast</u> unknown unknown 09 DESCRIPTION OF WELLS Including useage, death, and in One well registered in Section 9 - Domestic - 140Ft. - Morthwest of site. 11 DISCHARGE AREA 10 RECHARGE AREA COMMENTS Groundwater discharge to During high river flow YES **社 YES COMMENTS** Scappoose Bay periods □ NO IV. SURFACE WATER O1 SURFACE WATER USE (Check one) B. IRRIGATION. ECONOMICALLY IMPORTANT RESOURCES C. COMMERCIAL, INDUSTRIAL D. NOT CURRENTLY USED XX A. RESERVOIR, RECREATION DRINKING WATER SOURCE 02 AFFECTED/POTENTIALLY AFFECTED BODIES OF WATER **AFFECTED** DISTANCE TO SITE NAME: Milton Creek (mi) Scappoose Bay \Box (mi) (mil V. DEMOGRAPHIC AND PROPERTY INFORMATION 02 DISTANCE TO NEAREST POPULATION 01 TOTAL POPULATION WITHIN TWO 131 MILES OF SITE THREE (3) MILES OF SITE CNE (1) MILE OF SITE NO OF PERSONS NO CEPERSONS 12 NUMBER OF BUILDINGS WITHIN TWO 121 MILES OF SITE 04 DISTANCE TO NEAREST OFF-SITE BUILDING 2,866

US PICPULATION WITHIN VICINITY OF SITE , Provide narrative description of nature of population within vicinar of site, e.g., rural, vitage, denser population

The land use in the vicinity of the plant is light industry. One and one half miles to the north is the City of St. Helens, OR Population - 7,000



POTENTIAL HAZARDOUS WASTE SITE

	HEICATION
PHETATE	DOOD 476100
OK.	D093476109

WETA	PART	SITE INSPE T 5 - WATER, DEMOGRAPI	CTION REPORT HIC, AND ENVIRO		ATA UR	D093476	in 109
VI. ENVIRONMENTAL INFORMA							
OI PERMEABILITY OF UNSATURATED Z		ne)					
□ A. 10 ⁻⁶ — 10-	-8 cm/sec	☐ 8. 10 ⁻⁴ - 10 ⁻⁶ cm/sec (□ С. 10-4 — 10-3 сл	n/sec XXO. GRE	EATER THAN 1	10 ⁻³ cm/sec	
02 PERMEABILITY OF BEDROCK (Chace of	one)		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
	10 ⁻⁶ cmrsect	B. RELATIVELY IMPERMEAE	BLE C. RELATIVE	LY PERMEABLE		PERMEABLE man 10 ⁻² cm/seci	
03 DEPTH TO BEDROCK	04 DEPTH O	OF CONTAMINATED SOIL ZONE	05 50IL pr	4			
(n)		Unknown (ft)		5-6.0			
GG NET PRECIPITATION	07 ONE YEA	AR 24 HOUR RAINFALL	08 SLOPE SITE SLOPE	DIRECTION OF	CITE SI OPE	TERRAIN AVERAC	CE SI ORE
		2.0 (in)	5_%	south	MIE SEO. C.	0-5	**************************************
SITE IS IN 100 YEAR FLO	ODPLAIN	D SITE IS ON BARR	RIER ISLAND, COASTA	AL HIGH HAZARD	AREA, RIVERI	NE FLOODWAY	
11 DISTANCE TO WETLANDS 15 acre minera			12 DISTANCE TO CRIT	TICAL HABITATION OF			
ESTUARINE		OTHER		2	2		
1 <		OHILI		- \	Vhitetail	.(mi) 1 deer	,
A(mi)	B	(mi)	ENDANGERE	ED SPECIES:	11100001	l ucci	
13 LAND USE IN VICINITY							
DISTANCE TO:		RESIDENTIAL AREAS: NATIO	THAT ISTATE PARKS.		ACCIONI THE		
COMMERCIAL/INDUSTRI	AL	FORESTS, OR WILDLIF		PRIME AC	AGRICULTUR G LAND	RAL LANDS AG LAND	
A (mi)		B	(mi)	C	(mi)	D	(mi)
14 DESCRIPTION OF SITE IN RELATION TO							
Owens-Corning Fibero Scappoose Bay and or light industrial.	glas Fil n the e	berboard plant is ast by Milton Cree	surrounded o ∍k. The are	on the wes ea to the	t and so north of	outh by f the plant	; is
		•					
			•				•
•				•			
					-		
VII. SOURCES OF INFORMATION	i idite specific re	ererences, e.g., state tiles, samble analysis, i	reportsi				
HCDA CCC Coil intone		Passand of Co	-1bio Count	L			
USDA-SCS-Soil interp USGA Topographical m US Census, 1980				iy;			÷

•					A
O FDA		'.	S WASTE SITE	<u></u>	I. IDENTIFICATION DI STATE I 02 SITENUMBER
SEPA	S PART 4 - PERMIT	SITE INSPECT			OR D093476109
	PART 4-7 LIBRAT	AND DEGOTION	TIVE III OIIIIA		
I. PERMIT INFORMATION	02 PERMIT NUMBER	03 DATE ISSUED	04 EXPIRATION DATE	1 05 COMMENTS	
1 TYPE OF PERMIT ISSUED (Check all that accept)			OTESTICATE	· ·	
Ď¾. NPOES	1643 J	Unknown		No discha	rge since Feb. 82
☐ 8. UIC		ļ			
XX C. AIR	82052085	Unknown		No discha	rge since Feb. 82
D. RCRA		<u> </u>		ļ	
DE. RCRA INTERIM STATUS			<u> </u>		
F. SPCC PLAN	Unknown	Unknown		ļ	
G. STATE. Specify				ļ <u>.</u>	
TH. LOCAL (Species)				<u> </u>	
CI. OTHER (Specific)					
CJ. NONE	·	<u> </u>	<u> </u>		·
II. SITE DESCRIPTION					
01 STORAGE/DISPOSAL (Check of that apply)	02 AMOUNT 03 UNIT OF	MEASURE 04 TI	REATMENT (Check at there	iopiy)	05 OTHER
☐ A. SURFACE IMPOUNDMENT _		🗆 A.	INCENERATION		XXA. BUILDINGS ON SITE
☐ B. PILES _		🗆 В.	UNDERGROUND INJ	ECTION	E A. BUILDINGS ON SITE
XX C. DRUMS. ABOVE GROUND	<u> 30 drums</u>	ØXc.	CHEMICALIPHYSIC	AL.	·
D. TANK, ABOVE GROUND		00.00	BIOLOGICAL		
ØXE. TANK, BELOW GROUND)il tank at boile	4			06 AREA OF SITE
F. LANDFILL _		1	SOLVENT RECOVER		175
⊠XG. LANDFARM	laste burned on s		OTHER RECYCLING	RECOVERY	, , , , , , , , , , , , , , , , , , ,
Δχ.: O. Δ. σ. σ	intil 1970.	LIES UH.	OTHER	ecry)	erese in the
I. OTHER	<u> </u>				·
C7 COMMENTS					
Gite has secondary trea	tment plant, mai	n componer	its of plant	are prima	ry claritier,
eration lagoon, second		stuage no	aing pona.	Drums con	tain latex
and silicone paint wast	te.				
	,				
IV. CONTAINMENT					
1 CONTAINMENT OF WASTES (Check Gree)	_,				•
A ADEQUATE, SECURE	XX B. MODERATE	C. INADEQ	UATE, POOR	D. INSECU	RE, UNSOUND, DANGEROUS
02 DESCRIPTION OF DRUMS, DIKING, LINERS,	BARRIERS, ETC.				
The sludge pond and aer	ration lagoon are	e unlined v	which would	allow leac	hate to escape.
ille studge polla and aei	acton tagoon are	2 uni inicu, i			- · · · - · · · · · · · · · · · · · · ·
Γ					
l_					

V. ACCESSIBILITY

JT WASTE SAGILY ACCESSIBLE. Z YES XXNO

02 COMMENTS

Although area is not completely fenced, the brush around river serves as a fence.

FI. SOURCES OF INFORMATION (Cité specific references le g. state (Les, sample enaiyais, réports)

Site interview with facilities manager, Marlene Warren; DEQ files; EPA files

		MC
B 2		
00	تنسط	₽

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 6 - SAMPLE AND FIELD INFORMATION

I. IDENT	IFICATION	
OR OR	°6093476109	ı

	_			
II. SAMPLES TAK	EN			· · · · · · · · · · · · · · · · · · ·
SAMPLETYPE		01 NUMBER OF SAMPLES TAKEN	02 SAMPLES SENT TO	OS ESTIMATED DATE RESULTS AVAILABLE
GROUNDWATER		None		
SURFACE WATE	₹			
WASTE				
AGR				
RUNOFF				
SPUL				·
SOIL				
VEGETATION				
OTHER				
IIL FIELD MEASU	REMENTS TA	KEN		
01 TYPE		02 COMMENTS	••	المعادر المعادية المعادر ==
None			· ·	:
			·	2 -
IV. PHOTOGRAPH	S AND MAPS	3		
01 TYPE I GROU	NO XX AERIAL	,	02 IN CUSTODY OF UWENS Corning Fiberglas St. Helens, C	JK
DI MAPS XXYES I NO	EPA :	ofmaps Seattle WA		
V. OTHER FIELD (ATA COLLE	CTED : Frovide namelive di	93C70/IOA1	
8				

VI. SOURCES OF INFORMATION (Cité appetitus perendes, e.g., state ties, sample analysis, readman

DEQ Files; EPA Files; Site interview with the facilities manager, Marlene Warren

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 7 OWNER INFORMATION

I. IDENTIFICATION

1 STATE 102 SITE NUMBER

0R D093476109

		PART 7 - OW	NER INFORMATION	<u> </u>	
L CURRENT OWNER(S)			PARENT COMPANY (# approach)		•
1 NAME		02 D+B NUMBER	OB NAME		109 D+8 NUMBER
Owens-Corning Fiberglas	s Corn	UZ UY B NUMBER	DO NAME		
DI STREET ADDRESS (P. D. Bon. RED #. etc.)	3 COIP.	04 SIC CODE	10 STREET ADDRESS (P.O. Box. AFD #. etc.)		11 SIC CODE
Fiberglas Tower					
is city	06 STATE	O7 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE
Toledo	ОН	43659			
OI NAME	<u> </u>	02 D+8 NUMBER	08 NAME		09 D+6 NUMBER
			·		
3 STREET ADDRESS (P.O. Box. RFD #. exc.)		04 SIC CODE	10 STREET AODRESS (P.O. Box. RFD #. etc.)		11SIC CODE
					1
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE
	ļ	1			1
DI NAME		02 D+8 NUMBER -	08 NAME		09 D+6 NUMBER
			1	•	
3 STREET ADDRESS (P O. Box. RFD #. etc.)		04 SIC CODE	10 STREET ADDRESS (P.O. Box. RFO F. etc.)		11SIC CODE
		1			•
D5 CITY	06 STATE	07 ZP CODE	12 CITY	13 STATE	14 ZIP CODE
	į		·	1	
1 NAVE		02 D+B NUMBER	08 NAME		09D+8MLMBER
		į	·	•	
173 STREET ADDRESS (P.O. Box. RFD #, ecc.)		04 SIC CODE	10 STREET ADDRESS IP. O. Box. RFD #. ONL.		11 SIC CODE
			· ·		
05 CITY	06 STATE	07 ZIP CODE	12 CITY	13 STATE	14 ZIP CODE
]	·		•
II. PREVIOUS OWNER(S) (Last most recent to		l	IV. REALTY OWNER(S) (# apportable: set /	mast recent first)	
01 NAME		02 D+8 NUMBER	01 NAME		02 D+8 NUMBER
Kaiser Gypsum]		-	
3 STREET ADDRESS IP O. Box. RFD #. etc.)		04 SIC CODE	03 STREET ADDRESS (P O. Box. AFD P. erc.)		04 SIC CODE
300 Lakeside Dr.		<u> </u>			
DS CITY	•	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE.
Oakland	CA	94612			•
1 NAME	1.0-	02 D+8 NUMBER	Dant & Russel Inc.		C2 D+8 NUMBER
Firtex Insulation Board	a co.				
3 STREET ADDRESS, P.O. Box, RFD# etc.)		04 SIC CODE	1221 SW Yamhill		04 SIC CODE
Old Portland Rd.	la ==	<u> </u>		IOS STATE	07 ZIP CODE
_St. Helens	OR STATE	07 ZIP CODE .	Portland	OR	UI AFCOUE
					02 D+6 NUMBER
INAME		02 D+8 NUMBER	OI NAME		US OT U NUMBER
		04 SIC CODE	03'STREET ADDRESS P. O. Box. RFD # etc.)		04 SIC CODE
STREET ADDRESS: PO Box HFD# aic I	•	U4 SIC CODE	OS STREET ADDRESS IP O. BOX. APD V BIC.)		
CITY	Inecres	V VIII CODE	OS CITY	Q6 STATE	D7 ZIP CODE
DSCITY	DESTATE	37 ZIP CODE	OS CITY	3331212	
L		·			
/, SOURCES OF INFORMATION (Cite and	secific references.	e.g., state fives, sample analys	sis, reports)		

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10. PAST RESPONSE ACTIVITIES

L IDENTIFICATION
OT STATE OZ SITE NUMBER
OR D093476109

PART 10-PA	ST RESPONSE ACTIVITIES	
I. PAST RESPONSE ACTIVITIES		
01 () A. WATER SUPPLY CLOSED 04 DESCRIPTION	02 DATE	03 AGENCY
None	·	03 AGENCY
01 C B. TEMPORARY WATER SUPPLY PROVIDED 04 DESCRIPTION	02 DATE	WARRY
None	02 DATE	03 AGENCY
01 C C PERMANENT WATER SUPPLY PROVIDED 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 D. SPILLED MATERIAL REMOVED 04 DESCRIPTION	UZ DATE	
None	·	03 AGENCY
01 (E. CONTAMINATED SOIL REMOVED 04 DESCRIPTION	02 DATE	WASHU!
None	·	03 AGENCY
01 C F. WASTE REPACKAGED 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 C G. WASTE DISPOSED ELSEWHERE 04 DESCRIPTION	OZ DATE	
None	02 DATE	03 AGENCY
01 H. ON SITE BURIAL 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 G I. IN SITU CHEMICAL TREATMENT 04 DESCRIPTION	OZ DATE	
None	02 DATE	03 AGENCY
01 © J. IN SITU BIOLOGICAL TREATMENT 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 G K. IN SITU PHYSICAL TREATMENT 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 IL ENCAPSULATION 04 DESCRIPTION	02 DATE	
None	02 DATE	03 AGENCY
01 G M. EMERGENCY WASTE TREATMENT 04 DESCRIPTION	02 DATE	
None		03 AGENCY
01 IN CUTOFF WALLS 04 DESCRIPTION	02 DATE	
None		O3 AGENCY
01 (2) O. EMERGENCY DIKING/SURFACE WATER DIVERSION 04 DESCRIPTION	02 DATE	OS AGENOT
None		03 AGENCY
01 CEP CUTOFF TRENCHES:SUMP 04 CESCRIPTION	O2 DATE	UJ AGENCI
None		
01 C Q. SUBSURFACE CUTOFF WALL 04 DESCRIPTION None	02 DATE	03 AGENCY
WORG		

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10 - PAST RESPONSE ACTIVITIES

1	I. IDENTIFICATION							
	OI STATE	02 SITE NUMBER						
	OR	D093476109						

17		
PAST RESPONSE ACTIVITIES (Continued)		
01 A. BARRIER WALLS CONSTRUCTED 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 S. CAPPING/COVERING 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 G T: BULK TANKAGE REPAIRED 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 D U. GROUT CURTAIN CONSTRUCTED 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 I V. BOTTOM SEALED 04 DESCRIPTION	02 DATE	
None		
01 ☐ W. GAS CONTROL 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 🗆 X. FIRE CONTROL 04 DESCRIPTION	02 DATE	03 AGENCY
None		
01 C Y. LEACHATE TREATMENT	02 DATE	03 AGENCY
04 DESCRIPTION None		
01 T. AREA EVACUATED	02 DATE	03 AGENCY
04 DESCRIPTION	•	
None		03 AGENCY
01 [: 1. ACCESS TO SITE RESTRICTED 04 DESCRIPTION	02 DATE	US AGENCT
None .		
01 C 2. POPULATION RELOCATED	02 DATE	03 AGENCY
04 DESCRIPTION		
None		an ACTIVAY
01 G 3. OTHER REMEDIAL ACTIVITIES 04 DESCRIPTION	02 DATE	03 AGENCY
None		

II. SOURCES OF INFORMATION (CLA Specific revenues), e.g., state (169), sample analysis, redorts)

EPA File; DEQ Files; Site interview with facilities manager, Marlene Warren



POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION

I. IDENTIFICATION

ORTATE BOSS 446109

IL ENFORCEMENT INFORMATION

01 PAST REGULATORY/ENFORCEMENT ACTION | YES XXNO

02 DESCRIPTION OF FEDERAL, STATE, LOCAL REGULATORY/ENFORCEMENT ACTION

III. SOURCES OF INFORMATION (Cite appetitic reterences, e.g., state tikes, sample enaivaira, reports)

EPA Files; DEQ Files

	EI	AC
--	----	----

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 8 - OPERATOR INFORMATION

I. IDENT	IFICATION
	02 SITE NUMBER
OR	D093476109

II. CURRENT OPERATOR (Provide a different from owner)			OPERATOR'S PARENT COMPANY (# acquirable)		
01 NAME 02 D+6 NUMBER			10 NAME		
o.					
	04 SIC CODE	12 STREET ADDRESS (P.O. Box. RFD #. etc.)		13 SIC CODE	
	1				
1		14 CITY	15 STATE	16 ZIP CODE	
OK	9/051				
st: prawae only	d different from towners	PREVIOUS OPERATORS' PARENT CO	MPANIES (#	applicable)	
		10 NAME		110+8 NUMBER	
	04 SIC CODE	12 STREET AODRESS (P.O. Box. AFD F. etc.)		13 SIC CODE	
			LE CTATE		
06 STATE	07 ZIP CODE	14 City	ISSIAIE	16 ZIP CODE	
			_	·	
URING THIS	PERIOD				
	00 D 1 D 4 H 14 4 C C D	10000		11 D+8 NUMBER	
	UZ D+6 NUMBER	TURAME			
1	IOA SIC CODE	12 STREET ADDRESS (P.O. Box. RED.A. arc.)		13 SIC CODE	
OR STATE	OZ ZIP CODE	14CITY	15 STATE	16 ZIP CODE	
SURING THIS	3 PERIOD				
	02 D+8 NUMBER	10 NAME		11 D+B NUMBER	
	•			•	
1	04 SIC CODE	12 STREET ADDRESS (P.O. Box. RFD #. etc.)		13 SIC CODE	
		· ·			
06 STATE	07 ZIP CODE	14 CITY	15 STATE	16 ZIP CODE	
URING THIS	PERIOD				
references, e	.g., state hine, particle energy	28. /000/TE J			
		Manlana Wannan			
	OB STATE OR OB STATE URING THIS	O2 D+8 NUMBER O3 O4 SIC CODE O6 STATE O7 ZIP CODE O6 STATE O7 ZIP CODE O2 D+8 NUMBER O4 SIC CODE O4 SIC CODE	02 D+8 MAMBER	02 D+8 NUMBER	

Site interview with the facilities manager, Marlene Warren

		SITE INSPI	ZARDOUS WASTE SITE ECTION REPORT TRANSPORTER INFORMATION	I. IDENTIFICATION 01 STATE 02 SITE NUMBER 0R D093476109	
II. ON-SITE GENERATOR					
O1 NAME		02 D+8 NUMBER			
Owens-Corning Fiberglas					
03 STREET ADDRESS IP O. Box. RFD 0. box.) Old Portland Rd.		04 SIC CODE			
DS CITY		07 ZIP CODE	_		
St. Helens	OR	97051			
III. OFF-SITE GENERATOR(S)					
01 NAME		02 D+8 NUMBER	01 NAME		02 D+8 NUMBER
None					
03 STREET ADDRESS (2 O Bod. AFD 9: etc.)		04 SIC CODE	03 STREET ADDRESS (P.O. Box. PFD# . exc.)		04 SIC CODE
05 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
)1 NAME	<u> </u>	02 D+8 NUMBER	01 NAME		02 D+8 NUMBER
OB STREET ADDRESS (P.O. Box. RFD #, MC.)		04 SIC CODE	03 STREET ADDRESS (P.O. Bas. APDe. car.)		04 SIC CODE
05 CITY	OB STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
			<u>l l de la companya d</u>		<u> </u>
IV. TRANSPORTER(S)					
Un known		02 D+8 NUMBER	01 NAME		02 D+8 NUMBER
3 STREET ADDRESS (P.C. Box. RFD # etc.)		04 SIC CODE	03 STREET ADDRESS (P.O. Ball ADDRESS)		04 SIC CODE
5 CITY	06 STATE	07 ZIP CODE	05 CITY	06 STATE	07 ZIP CODE
D1 NAME		02 D+8 NUMBER	01 NAME		02 D+8 NUMBER
3 STREET ADCRESS (P.U. Box, AFD # 91c.)		04 SIC CODE	03 STREET ADDRESS (P.O. Box. (PD+) are (04 SIC CODE

05 CITY

06 STATE 07 ZIP CODE

V. SOURCES OF INFORMATION (Cae apecific references), e.g., state files, sample analysis, reports)

06 STATE 07 ZIP CODE